

# HOME INSPECTION REPORT



161 Glendale Ave  
Toronto

Prepared for: Kevin Alvarez

Prepared by: Bob Papadopoulos P.Eng., RHI \*

Inspection Date: April 1 2016



[www.redbrickinspections.ca](http://www.redbrickinspections.ca)  
[bob@redbrickinspections.ca](mailto:bob@redbrickinspections.ca)  
416-829-6655

\* please see credentials at end of report

## SIGNIFICANT ITEMS

*This page should not be considered as the complete report.  
Please read all other forms contained within the Home  
Inspection Report*

*For the purposes of this report,  
the front of the house is considered  
to be facing: West*

## ROOFING

The majority of the roof surfaces through-out are overall in good repair. The east sloped surface will require replacement in the short term.

## EXTERIOR

The wall surfaces are in good repair. The retaining walls and front steps are in good repair. See details for repairs and maintenance.

## STRUCTURE

Overall well built house

## ELECTRICAL

The 100 AMP service size is adequate and the wiring has been upgraded.

## HEATING

8-yr-old high-efficiency forced-air gas furnace with a typical life expectancy of 20-yrs.

COOLING/  
HEAT PUMPS

Approx. 10-yr-old air-conditioner with a typical life expectancy of 15-yrs.

INSULATION/  
VENTILATION

Restricted access to roof and wall spaces therefore insulation not determined.

## PLUMBING

The watermain has been upgraded and the supply piping in the house is copper and plastic with good water pressure overall. The main waste drain has been upgraded. 6-yr-old on demand water heater.

## INTERIOR

Overall well maintained. The windows have been upgraded.

## OVERALL RATING

The following rating reflects both the original quality of construction and the *overall* current condition of the home, based on a comparison to *similar* homes.



Below Typical

Typical

Above Typical

*Prior to reviewing the Home Inspection Report please read the Terms and Conditions of the Home Inspection and the Standards of Practice of the Canadian Association of Home and Property Inspectors available online at [www.redbrickinspections.ca](http://www.redbrickinspections.ca).*

Description				
Roofing Material:	Location:	Leakage Probability:	Chimney(s) Type:	Location:
Slate	West Slope:	Low	Brick:	North
Modified Bitumen:	Flat:	Low	Brick Abandoned:	East
Asphalt Shingles:	East Slope:	High		
Plastic/Rubber:	Porch(s):	Low		
Limitations				
Roof Inspected By:	Access Limited By:	Chimney Access Limited By:		
Walking On				
Ref#*	Observations/Recommendations			
	<p>West Slope: <a href="#">slates overall in good repair, require ongoing monitoring and maintenance</a></p> <div style="display: flex; justify-content: space-around;">   </div> <p>Flat Surface: <a href="#">newer surfaces in good repair</a></p> <div style="display: flex; justify-content: space-around;">   </div> <p>East Slope: <a href="#">aging, damaged shingles surface, budget to replace within 1-yr</a></p> <div style="display: flex; justify-content: space-around;">  </div> <p>Porch(s): <a href="#">newer plastic imitation slate surface in good repair</a></p> <div style="display: flex; justify-content: space-around;">  </div> <p>Chimney(s): <a href="#">overall well maintained</a></p>			
<p><a href="#">Note: Recommend Annual Maintenance Contract for Roof Surface, Flashing Details and Chimney(s)</a></p>				

## Description

Gutters & Downspouts: Aluminum:	Downspout(s) Discharge: Above Grade	Lot Topography: Flat Away From House	Walls & Wall Structures: Brick Wood siding Masonry Retaining Wall
------------------------------------	--	--	--

## Limitations

Exterior Inspection from Ground Level

## Observations/Recommendations

\*\*Gutters/Downspouts: requires general repairs and maintenance

Soffit &amp; Facia: requires general repairs and maintenance

WALL SURFACES: overall well maintained



DOORS/WINDOWS: overall well maintained

PORCH requires general repairs and maintenance

Step(s): should provide hand rails for safety




\*\*Walk(s): cracked concrete surfaces, step repairs, budget to replace  
 seal gaps at wall around perimeter to minimize moisture in basement,  
 new drain at rear though portion of pipe is older as observed  
 form the basement floor drain at rear window- drain may require repair



RETAING WALL(s): overall in good repair

Note: Maintain Gutters &amp; Downspouts annually. Extend Downspouts at least 6-feet away from the house

\*\* Any or all these items may contribute to **Basement Leakage**. Please see Interior Form

Description				
Configuration:	Foundations:	Floor :	Walls :	Roof/Ceiling Framing:
Basement:	Stone	Wood Joists	Masonry (Double-Brick)	Wood Rafters/Joists
Crawl Space:	Not Visible		Wood Frame (Siding)	
Limitations				
Restricted Access to:	Foundation Wall Not Visible: <u>60</u> %			
<a href="#">Wall Space</a> <a href="#">Roof Space</a> <a href="#">Crawl Space</a>				
Observations/Recommendations				
<p>FOUNDATIONS: <a href="#">basement: spalling damaged parging - repair as required or if renovating basement, overall not critical as long as mortar is in good repair</a></p> <p>FLOORS/WALLS <a href="#">rear extension: wood sill/joists are below grade and prone to damage, overall this is an older condition, digging around perimeter and repairing and sealing recommended</a></p>  <p>FLOORS: <a href="#">sagging floors not usual for older house, basement at front - joist cracked-minor repair</a></p> <p>WALLS:</p> <p>Masonry Arch: <a href="#">at rear of house requires repair though this is an older condition</a></p>  <p>Stair Opening: <a href="#">basement: loose joists at header connection though older condition: can be provided with hanger</a></p> 				

**Description**

Service Size: <b>100</b>	AMP (240volts)	Service Entrance Cable:	Distribution Wire:
Main Disconnect/Service Box		Location: <b>Overhead</b>	<b>Copper</b>
Rating: <b>100</b> AMP		Type of material: <b>Not Visible</b>	
Description: <b>Breakers</b>			
Location: <b>Basement</b>			
Distribution Panel	System Grounding:		
Rating: <b>100</b> AMP	Description: <b>Copper</b>		
Description: <b>Breakers</b>	Location: <b>Water Pipe</b>	Ground Fault Circuit Interrupter:	
Location: <b>Basement</b>		Location: <b>Outside</b>	
Auxiliary Panel(s):	Outlets	<b>Bathroom(s)</b>	
Rating: AMP	Description: <b>Grounded</b>		
Description:	Number of Outlets: <b>Typical</b>	Arc Fault Circuit Interrupter:	
Location:		Location: <b>Panel-Bedrooms</b>	

**Limitations****Main Disconnect Cover Not Removed**

Ref#\*

**Observations/Recommendations**SERVICE PANEL: **upgraded panel in good repair**BRANCH WIRING: **based on random sampling the wiring has been upgraded**

Note 1: All recommendations are safety issues - Treat them as high priority.

Note 2: Please ensure accurate labeling on panels.

Description						
Description:	Efficiency:	Rated Input:	Approx. Age:	Life Expectancy:	Fuel:	Shut Off at:
Forced Air Furnace:	High	75 x1000BTU/hr	8 yrs.	20 yrs.	Gas	Meter-Exterior
Exhaust Vent Arrangement: Plastic Through-Wall Vent						
Limitations					Furnace Performance	
Heat Loss Calculations Not Done					Supply Temp F:	120
Heat Exchanger- Inaccessible					Return Temp F:	70
Ref#*	Observations/Recommendations					

FORCED AIR FURNACE: service annually

Induced Draft Fan: noisy - may require replacement in short term



Ducts: older duct arrangement in some areas though typical for age of house

Registers: rusting at front underside




master bedroom register: could not find

basement: loose connection behind furnace





Description			
Description:	Cooling Capacity:	Approx. Age:	Typical Life Expectancy:
Air Conditioner (air-cooled):	18 x1,000 BTU/hr	10 yrs. old	15 yrs.
Limitations			Cooling Performance
Cannot Test With Low Outdoor Temp			Supply Temp F:
			Return Temp F:
Ref#*	Observations/Recommendations		
	<p>AIR CONDITIONER: not tested: should be serviced before using capacity possibly lower for size of house, may require additional cooling unit for 3rd level, monitor performance</p> 		



**Description**

Material:	Location	R-Value	Air/Vapour Barrier:	Venting:
				Roof

**Limitations**

Access Not Gained To Wall Space

Access Not Gained To Crawl Space



Access Not Gained To Roof Space

Ref#\*

**Observations/Recommendations**

cannot determine if insulation is present, typically installed during renovations for homes of this age

Note: adding insulation is considered an improvement rather than a repair

Description		
Service Piping into House:	Main Shut Off Valve at:	Water Flow (Pressure):
Copper	Basement-Front	Adequate
Supply Piping & Pump(s):	Waste Piping & Pump(s):	Water Heater
Copper	Plastic	Type: Tankless
Plastic	Cast Iron	Fuel Type: Gas
		Capacity: N/A
		Age Yrs.: 6
		Life Expectancy: 15
Limitations		
Isolating/Relief Valves & Main Shut Off Valves Not Tested	Concealed Plumbing not Inspected	
Kitchen and Laundry Appliances Were Not Inspected	Tub/Sink Overflows Not Tested	
Ref#*	Observations/Recommendations	
	<p>SUPPLY PIPING:</p> <p>WATERMAIN: upgraded to copper</p> <p>Piping: plastic supply piping is connected with brass fittings- some brands have been know to leak - should be monitored</p> <p>WASTE PIPING:</p> <p>Basement Floor Drain: upgraded with new main waste drain however no backflow valve observed- recommended especially if renovating basement</p>  <p>basement rear floor under window: older drain that services exterior walk drain - may require replacement</p> <p>older drain in basement washroom is older as well</p> <p>Piping: older waste drains in basement - replace if required or if renovating</p> <p>WATER HEATER: missing drip tube for safety valve</p> 	

**Description**

Floor Finishes:	Wall Finishes:	Ceiling Finishes:	Windows:	Exterior Doors:
Wood	Plaster/Drywall	Plaster/Drywall	Single/Double Hung	Wood
Carpet			Fixed	
Resilient				
Fireplaces:	Fireplace Fuel:			
Non-Functional				

**Limitations**

Restricted/No Access To: \_\_\_\_\_ Foundation Not Visible 60 %  
CO Detectors, Security Systems, Central Vacuum, Chimney Flues Not Inspected Drainage Tile Not Visible

Ref#\*

**Observations/Recommendations**

Ceilings: repair in some areas, damaged in kitchen - possibly from older leaking  
Floors/Walls/Ceilings: overall in good repair  
Trim/Cabinets/Counters: overall in good repair

Windows/Doors: overall in good repair

\*Evidence of Basement Leakage: typical efflorescence, staining and dampness for older foundation  
see steps below  
recommend damp-proofing foundation if finishing/renovating basement

CO/Smoke detectors: please ensure one per level each with annual maintenance, this is a life safety concern and mandatory by law

\*\* Steps recommended in order to minimize basement leakage

1. gutters, downspouts, grading, driveways: ongoing maintenance and repair/see Exterior
2. cracks/form ties on foundation: monitor/repair as required
3. excavation/damp-proofing: monitor basement, consider step 3 as a last resort should leaking persist



### **Bob Papadopoulos P.Eng, RHI**

---

- **Over 14 years of building inspecting experience in Toronto and the GTA**
- **Over 4,000 residential and commercial buildings inspected**

Bob has inspected over 4,000 residential and commercial buildings of various descriptions and reporting on conditions of major systems including structure, building envelope and mechanical systems, specific problem investigations and pre-renovation inspections. In the past Bob has helped train Home Inspectors and assisted in the creation of educational courses on home inspecting as well as taught Home Inspection courses at Seneca College. Bob also has experience in the construction industry inspecting many large scale projects through-out the GTA. He also served in the Canadian Navy as a Marine Mechanic and Ships Team Diver.

### **Professional Designations**

- P.Eng. (Professional Engineer of Ontario) <http://www.peo.on.ca/>
  - RHI Registered Home Inspector <http://www.oahi.com/>
  - Certified Energy Auditor
-